

TYPICAL WIRING DIAGRAM

SPLIT PHASE 120/230VAC (L1, L2, N, Ground)

THIS WIRING DIAGRAM IS FOR SPLIT PHASE SYSTEMS THAT DO NOT HAVE A TRANSFORMER

